

FORM 3510-3  
**EPA**  
 RCRA  
 U.S. ENVIRONMENTAL PROTECTION AGENCY  
**HAZARDOUS WASTE PERMIT APPLICATION**  
 Consolidated Permits Program  
 (This information is required under Section 3005 of RCRA.)

I. EPA I.D. NUMBER  
 S  
 F

## FOR OFFICIAL USE ONLY

APPLICATION APPROVED  
 DATE RECEIVED (yr., mo., & day)  
 33 24 29

COMMENTS

Wd 169716  
 2C 5-19-83

## II. FIRST OR REVISED APPLICATION

Place an "X" in the appropriate box in A or B below (mark one box only) to indicate whether this is the first application you are submitting for your facility or a revised application. If this is your first application and you already know your facility's EPA I.D. Number, or if this is a revised application, enter your facility's EPA I.D. Number in Item I above.

## A. FIRST APPLICATION (place an "X" below and provide the appropriate date)

☒ 1. EXISTING FACILITY (See instructions for definition of "existing" facility. Complete item below.)

☐ 2. NEW FACILITY (Complete item below.)

FOR EXISTING FACILITIES, PROVIDE THE DATE (yr., mo., & day) OPERATION BEGAN OR THE DATE CONSTRUCTION COMMENCED (use the boxes to the left)

FOR NEW FACILITIES, PROVIDE THE DATE (yr., mo., & day) OPERATION BEGAN OR IS EXPECTED TO BEGIN

## B. REVISED APPLICATION (place an "X" below and complete Item I above)

☐ 1. FACILITY HAS INTERIM STATUS

AMENDED APPLICATION

☐ 2. FACILITY HAS A RCRA PERMIT

## III. PROCESSES - CODES AND DESIGN CAPACITIES

A. PROCESS CODE - Enter the code from the list of process codes below that best describes each process to be used at the facility. Ten lines are provided for entering codes. If more lines are needed, enter the code(s) in the space provided. If a process will be used that is not included in the list of codes below, then describe the process (including its design capacity) in the space provided on the form (Item III-C).

B. PROCESS DESIGN CAPACITY - For each code entered in column A enter the capacity of the process.

1. AMOUNT - Enter the amount.

2. UNIT OF MEASURE - For each amount entered in column B(1), enter the code from the list of unit measure codes below that describes the unit of measure used. Only the units of measure that are listed below should be used.

PROCESS	PROCESS CODE	APPROPRIATE UNITS OF MEASURE FOR PROCESS DESIGN CAPACITY
<b>Storage:</b>		
CONTAINER (barrel, drum, etc.)	S01	GALLONS OR LITERS
TANK	S02	GALLONS OR LITERS
WASTE PILE	S03	CUBIC YARDS OR CUBIC METERS
SURFACE IMPOUNDMENT	S04	GALLONS OR LITERS
<b>Disposal:</b>		
INJECTION WELL	D79	GALLONS OR LITERS
LANDFILL	D80	ACRE-FEET (the volume that would cover one acre to a depth of one foot) OR HECTARE-METER
LAND APPLICATION	D81	ACRES OR HECTARES
OCEAN DISPOSAL	D82	GALLONS PER DAY OR LITERS PER DAY
SURFACE IMPOUNDMENT	D83	GALLONS OR LITERS

## Treatment:

PROCESS	PROCESS CODE	APPROPRIATE UNITS OF MEASURE FOR PROCESS DESIGN CAPACITY
TANK	T01	GALLONS PER DAY OR LITERS PER DAY
SURFACE IMPOUNDMENT	T02	GALLONS PER DAY OR LITERS PER DAY
INCINERATOR	T03	TONS PER HOUR OR METRIC TONS PER HOUR; GALLONS PER HOUR OR LITERS PER HOUR
OTHER (Use for physical, chemical, thermal or biological treatment processes not occurring in tanks, surface impoundments or incinerators. Describe the processes in the space provided; Item III-C.)	T04	GALLONS PER DAY OR LITERS PER DAY



3058053

UNIT OF MEASURE	UNIT OF MEASURE CODE	UNIT OF MEASURE	UNIT OF MEASURE CODE	UNIT OF MEASURE	UNIT OF MEASURE CODE
GALLONS	G	LITERS PER DAY	V	ACRE-FEET	A
LITERS	L	TONS PER HOUR	D	HECTARE-METER	F
CUBIC YARDS	Y	METRIC TONS PER HOUR	W	ACRES	B
CUBIC METERS	C	GALLONS PER HOUR	E	HECTARES	Q
GALLONS PER DAY	U	LITERS PER HOUR	H		

EXAMPLE FOR COMPLETING ITEM III (shown in line numbers X-1 and X-2 below): A facility has two storage tanks, one tank can hold 200 gallons and the other can hold 400 gallons. The facility also has an incinerator that can burn up to 20 gallons per hour.

DUP

LINE NUMBER	A. PROCESS CODE (from list above)	B. PROCESS DESIGN CAPACITY		FOR OFFICIAL USE ONLY	LINE NUMBER	A. PROCESS CODE (from list above)	B. PROCESS DESIGN CAPACITY		FOR OFFICIAL USE ONLY
		1. AMOUNT (specify)	2. UNIT OF MEASURE (enter code)				1. AMOUNT	2. UNIT OF MEASURE (enter code)	
X-1	S02	600	G		5				
X-2	T03	20	E		6				
1	D80	17.906	A		7				
2					8				
3					9				
4					10				

### III. PROCESSES (continued)

C. SPACE FOR ADDITIONAL PROCESS CODES OR FOR DESCRIBING OTHER PROCESSES (code "T04"). FOR EACH PROCESS ENTERED HERE INCLUDE DESIGN CAPACITY.

### IV. DESCRIPTION OF HAZARDOUS WASTES

- A. EPA HAZARDOUS WASTE NUMBER** — Enter the four-digit number from 40 CFR, Subpart D for each listed hazardous waste you will handle. If you handle hazardous wastes which are not listed in 40 CFR, Subpart D, enter the four-digit number(s) from 40 CFR, Subpart C that describes the characteristics and/or the toxic contaminants of those hazardous wastes.
- B. ESTIMATED ANNUAL QUANTITY** — For each listed waste entered in column A estimate the quantity of that waste that will be handled on an annual basis. For each characteristic or toxic contaminant entered in column A estimate the total annual quantity of all the non-listed waste(s) that will be handled which possess that characteristic or contaminant.
- C. UNIT OF MEASURE** — For each quantity entered in column B enter the unit of measure code. Units of measure which must be used and the appropriate codes are:

ENGLISH UNIT OF MEASURE	CODE
POUNDS.....	P
TONS.....	T

METRIC UNIT OF MEASURE	CODE
KILOGRAMS.....	K
METRIC TONS.....	M

If facility records use any other unit of measure for quantity, the units of measure must be converted into one of the required units of measure taking into account the appropriate density or specific gravity of the waste.

### D. PROCESSES

#### 1. PROCESS CODES:

**For listed hazardous waste:** For each listed hazardous waste entered in column A select the code(s) from the list of process codes contained in Item III to indicate how the waste will be stored, treated, and/or disposed of at the facility.

**For non-listed hazardous wastes:** For each characteristic or toxic contaminant entered in column A, select the code(s) from the list of process codes contained in Item III to indicate all the processes that will be used to store, treat, and/or dispose of all the non-listed hazardous wastes that possess that characteristic or toxic contaminant.

**Note:** Four spaces are provided for entering process codes. If more are needed: (1) Enter the first three as described above; (2) Enter "000" in the extreme right box of Item IV-D(1); and (3) Enter in the space provided on page 4, the line number and the additional code(s).

#### 2. PROCESS DESCRIPTION: If a code is not listed for a process that will be used, describe the process in the space provided on the form.

**NOTE: HAZARDOUS WASTES DESCRIBED BY MORE THAN ONE EPA HAZARDOUS WASTE NUMBER** — Hazardous wastes that can be described by more than one EPA Hazardous Waste Number shall be described on the form as follows:

- Select one of the EPA Hazardous Waste Numbers and enter it in column A. On the same line complete columns B, C, and D by estimating the total annual quantity of the waste and describing all the processes to be used to treat, store, and/or dispose of the waste.
- In column A of the next line enter the other EPA Hazardous Waste Number that can be used to describe the waste. In column D(2) on that line enter "included with above" and make no other entries on that line.
- Repeat step 2 for each other EPA Hazardous Waste Number that can be used to describe the hazardous waste.

**EXAMPLE FOR COMPLETING ITEM IV (shown in line numbers X-1, X-2, X-3, and X-4 below)** — A facility will treat and dispose of an estimated 900 pounds per year of chrome shavings from leather tanning and finishing operation. In addition, the facility will treat and dispose of three non-listed wastes. Two wastes are corrosive only and there will be an estimated 200 pounds per year of each waste. The other waste is corrosive and ignitable and there will be an estimated 100 pounds per year of that waste. Treatment will be in an incinerator and disposal will be in a landfill.

LINE NO.	A. EPA HAZARD. WASTE NO. (enter code)	B. ESTIMATED ANNUAL QUANTITY OF WASTE	C. UNIT OF MEASURE (enter code)	D. PROCESSES	
				1. PROCESS CODES (enter)	2. PROCESS DESCRIPTION (if a code is not entered in D(1))
X-1	K 0 5 4	900	P	T 0 3 D 8 0	
X-2	D 0 0 2	400	P	T 0 3 D 8 0	
X-3	D 0 0 1	100	P	T 0 3 D 8 0	
X-4	D 0 0 2				included with above

EPA I.D. NUMBER (enter from page 1)													FOR OFFICIAL USE ONLY											
W													W DUP											
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15													1 2 3 4 5 6 7 8 9 10 11 12 13 14 15											
IV. DESCRIPTION OF HAZARDOUS WASTES (continued)																								
WASTE NO.	A. EPA HAZARD. WASTE NO. (enter code)				B. ESTIMATED ANNUAL QUANTITY OF WASTE				C. UNIT OF MEASURE (enter code)		D. PROCESSES													
											1. PROCESS CODES (enter)					2. PROCESS DESCRIPTION (if a code is not entered in D(1))								
1	K	0	0	1	190 MINIMUM				T	D 8 0					BOTTOM, MULTI-CONE AND BAGHOUSE									
2	D	0	0	4	TO										ASH FROM WASTE WOOD BOILER PLANT									
3					240 MAXIMUM										CONTAMINATED WITH RESIDUE FROM									
4					OF										BURNING OF KOOL SLUDGE AND,									
5					BOILER ASH										THROUGH SYSTEM UPSET, CCA SLUDGE									
6																								
7																								
8																								
9																								
10																								
11																								
12																								
13																								
14																								
15																								
16																								
17																								
18																								
19																								
20																								
21																								
22																								
23																								
24																								
25																								
26																								

## IV. DESCRIPTION OF HAZARDOUS WASTES (continued)

E. USE THIS SPACE TO LIST ADDITIONAL PROCESS CODES FROM ITEM D(1) ON PAGE 3.

EPA I.D. NO. (enter from page 1)

1	2	3	4	5	6	7	8	9	0	1	2	3	4	5	6	7	8	9	0

## V. FACILITY DRAWING

All existing facilities must include in the space provided on page 5 a scale drawing of the facility (see instructions for more detail).

## VI. PHOTOGRAPHS

All existing facilities must include photographs (aerial or ground-level) that clearly delineate all existing structures; existing storage, treatment and disposal areas; and sites of future storage, treatment or disposal areas (see instructions for more detail).

## VII. FACILITY GEOGRAPHIC LOCATION

LATITUDE (degrees, minutes, &amp; seconds)

4	5	4	9	5	0
65	66	67	68	69	70

LONGITUDE (degrees, minutes, &amp; seconds)

1	2	2	4	2	0	1
72	73	74	75	76	77	78

## VIII. FACILITY OWNER

☐ A. If the facility owner is also the facility operator as listed in Section VIII on Form 1, "General Information", place an "X" in the box to the left and skip to Section IX below.

☐ B. If the facility owner is not the facility operator as listed in Section VIII on Form 1, complete the following items:

1. NAME OF FACILITY'S LEGAL OWNER

2. PHONE NO. (area code &amp; no.)

ELMER C. MUFFETT

206-887-3130

3. STREET OR P.O. BOX

4. CITY OR TOWN

5. ST.

6. ZIP CODE

3510 N.W. 289th St.

RIDGEFIELD

WA

98642

## IX. OWNER CERTIFICATION

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

A. NAME (print or type)

B. SIGNATURE

C. DATE SIGNED

ELMER C. MUFFETT

Elmer C. Muffett

5/19/83

## X. OPERATOR CERTIFICATION

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

A. NAME (print or type)


B. SIGNATURE

C. DATE SIGNED

 MARK T. MOOTHART  
 TREASURER / GENERAL MANAGER

Mark T. Moothart

5/19/83





# PACIFIC WOOD TREATING CORPORATION

P.O. BOX 518/111 W. DIVISION ST./RIDGEFIELD, WA 98642  
PHONE: (206) 887-3562; FROM PORTLAND: 283-3017

PACKAGES, CORRESPONDENCE  
AND INVOICES REGARDING  
THIS ORDER.

SHOW THIS NUMBER

41073

TO: SWEET, EDWARDS & ASSOCIATES  
P.O. Box 328  
KELSO, WASHINGTON 98626

SHIP TO:

ORDER DATE 05-13-83	TERMS Net 30 Days	SHIP VIA N/A	DATE REQUIRE AT P.W.T. PLANT
PHONE 423-3580	WASHINGTON STATE SALES TAX NO. C-064 000 753	TAXABLE FOR OUR OWN USE <input checked="" type="checkbox"/> FOR RESALE <input type="checkbox"/> FOR DUTY OF STATE USE AND IS NOT SUBJECT TO WASHINGTON SALES TAX <input type="checkbox"/>	F.O.B. N/A

See Below

ITEM	QUANTITY	UNIT	PART NUMBER	DESCRIPTION	AMOUNT
1	Lot			Disposal Site Hyrdogeological/Monitoring Evaluation, PHASE I, as follows:	
				1. Evaluate waste stream and potential leachate/monitoring constituents as related to regulatory requirements.	
				2. Review published soils/geologic data.	
				3. Field locate beneficial water uses; - surface water rights - water wells/logs.	
				4. Develop local water table potentiometric surface map; - survey or project measuring point elevations. - measure depth(s) to water.	
				5. Evaluate potential for use of existing adjacent wells for incorporation in monitoring network.	
				6. Recommend monitoring layout, sampling specifications and parameters for testing in a summary report (5 copies).	
				7. Meet with Pacific Wood Treating staff and regulatory agency personnel to finalize the monitoring plan.	
(continued on page 2 - Invoice 41073)					

IF YOU ARE UNABLE TO ACCEPT THIS ORDER AS SPECIFIED PLEASE SO ADVISE

BY WIRE IMMEDIATELY

INVOICE IN DUPLICATE

BY

PACIFIC WOOD TREATING CORPORATION

VENDOR COPY

"The provisions of Executive Order 11246 and amendments thereto, are hereby incorporated by reference, and the seller represents, by acceptance of this purchase order, that he will comply with such regulations."



# PACIFIC WOOD TREATING CORPORATION

P.O. BOX 518/111 W. DIVISION ST./RIDGEFIELD, WA 98642  
PHONE: (206) 887-3562; FROM PORTLAND: 283-3017

FOR VALUES CORRESPONDING  
AND INVOICES REGARDING  
THIS ORDER.

**SHOW THIS NUMBER**

41073 (Pge 2 of 2)

TO:

SWEET, EDWARDS & ASSOCIATES  
P.O. BOX 328  
KELSO, WASHINGTON 98626

SHIP TO:

ORDER DATE 05-13-83	TERMS Net 30 Days	SHIP VIA N/A			DATE REQUIRED AT P.W.T. PLANT
PHONE 423-3580	WASHINGTON STATE SALES TAX NO. C-064 000 753	TAXABLE FOR OUR OWN USE <input checked="" type="checkbox"/>	FOR RESALE <input type="checkbox"/>	FOR OUT OF STATE USE AND IS NOT SUBJECT TO WASHINGTON SALES TAX <input type="checkbox"/>	F.O.B. N/A
ITEM	QUANTITY	UNIT	PART NUMBER	DESCRIPTION	AMOUNT

PHASE I - continued

8. Assess current hazards/liability evaluation and options.
9. Assistance in evaluating:
  - Removal to secure site
  - Closeout
    - .. Topography
    - .. Materials Balance
    - .. Moisture Balance with Grading and Drainage

PHASE I SERVICES NOT TO EXCEED

\$2400.00

It is agreed that item 9 may or may not be included in the not to exceed figure of \$2400.00. Vendor is to advise and a suitable change order will be issued if required or deemed advisable.

Confirms verbal order of our Vince McQuiggin and Sweet, Edwards Quotation of March 30, 1983.

Evaluation to be completed by June 3, 1983.

**IF YOU ARE UNABLE TO ACCEPT THIS ORDER AS SPECIFIED PLEASE SO ADVISE BY WIRE IMMEDIATELY**  
INVOICE IN DUPLICATE

"The provisions of Executive Order 11246 and amendments thereto, are hereby incorporated by reference, and the seller represents, by acceptance of this purchase order, that he will comply with such regulations."

BY *Holden Tate*  
PACIFIC WOOD TREATING CORPORATION

VENDOR COPY

